- Home
- Part Number Search
- Document Search
- CAD Model Search
- Text Search
- Alternate/Lead Free Part Search
- Multiple Part Comparison
- Alphabetical Search
- Brand Search
- Industry Product Search
- Product Type Search
- Product Family Search
- Competitor Cross Reference
- Lead Free Solutions
- Tool Search
- Help/Glossary

Sockets

Plug Adapter Assemblies

AMP **616-AG1** Active Active RoHS Compliant RoHS Compliant

(Tyco Electronics P/N: 2-1437515-8)

Search for Parts

Document links for this part cannot be displayed. Your browser does not support inline frames or is currently configured not to display inline frames. Inline frames are supported in both Internet Explorer 5 and Netscape 6, as well as all later versions of these browsers.

Related Part Information		
General Information	**eCommerce**	**Related Part Information**
General Info Sales Info Assembly Subcontractors	Pricing Product Availability	Tooling

Searchable Features:

Brand:	AMP
RoHS/ELV Compliance:	RoHS compliant, ELV compliant
Lead Free Solder Process:	Reflow solder capable to 245°C
Product Type:	Assembly (Insulator and Pins)
No. of Pins:	16
Pin Style:	Round
Pin Plating:	Gold
Row-to-Row Spacing (mm [in]):	7.62 [0.300]

Other Properties:

RoHS/ELV Compliance History:	Always was compliant
Pin Material:	Phosphor Bronze
Insulator Material:	Thermoplastic Polyester
Insulator Flammability Rating:	UL94V-0
Operating Temperature (°C):	-65 – +125
Product Series:	600 Series

Copyright and Privacy Statement

Visit Tyco International, Ltd.

i2 Technologies US, Inc.
15445 Innovation Drive
San Diego, CA 92128

i2 Technologies US, Inc.

HTML Pages converted to PDF Document

This document contain component information from the manufacturer's website which are not available in a revision controlled document from the manufacturer. To facilitate the addition of these parts into the Electronics Database, we are converting the HTML pages related to that part, from the manufacturer's website into Adobe PDF format. The contents of this document is based on the information provided on the manufacturer's website, therefore the information may have been changed by the manufacturer since this was created.